



LABORATORY REPORT

Example Client, XYZ123
1234 Warde Road
Ann Arbor MI 48108

EXAMPLE, REPORT W
WX0000003827 M 07/08/1978 45 Y

Referral Testing

Collected: 10/06/2023 09:04 Received: 10/06/2023 09:04

<u>Test Name</u>	<u>Result</u>	<u>Flag</u>	<u>Ref-Ranges</u>	<u>Units</u>	<u>Site</u>
HBsAg Cadaver/Hemolyzed, S	Reactive	AB	Negative		MMRL

Screen is reactive. Confirmatory test is required.

Test Performed by:
Mayo Clinic Laboratories - Rochester Superior Drive
3050 Superior Drive NW, Rochester, MN 55901

HBsAg Confirm Cadav/Hemol, S	Negative		Negative		MMRL
------------------------------	----------	--	----------	--	------

Confirmatory test is the definitive test for true HBsAg status.

Test Performed by:
Mayo Clinic Laboratories - Rochester Superior Drive
3050 Superior Drive NW, Rochester, MN 55901

Performing Site:

MMRL: MAYO MEDICAL REFERENCE LAB 3050 Superior Drive NW Rochester MN 55901

Reported Date: 2023.10.06 9:04

LAB: L - LOW, H - HIGH, AB - ABNORMAL, C - CRITICAL, . - NOT TESTED

F406000005
WX0000003827

Ordered By: KAJAL SITWALA, MD, PhD
WX00000000002365

Printed D&T: 10/06/23 09:04

Kajal V. Sitwala, MD, PhD - Medical Director

Form: MM RL1

PAGE 1 OF 1